

ALM0054 - Resiliency in Effect

DESCRIPTION

The CCM server has detected that one or more devices being monitored have failed over to their resilient controller.

SEVERITY

Minor

IMPACT

None. This alarm is only an indicator that resiliency has been detected.

APPLIES TO

7.0 and newer

Keywords: Resiliency in Effect ALM0054

Last Modified By: dfontaine, Friday, May 08, 2015
<http://micc.mitel.com/kb/KnowledgebaseArticle51547.aspx>

Friday, August 12, 2022