

ALM0077 - System Identification

DESCRIPTION

There is an issue with the System Identification setting on the PBX.

Enter a unique number between 000 and 999, which identifies the system in SMDR reports. This is operational and the default is blank.

SEVERITY

Minor

IMPACT

This is a required field based on Standardized Network OLI being enabled. Each media server should have a unique System Identification number assigned.

TROUBLESHOOTING STEPS

1. Open the **3300 ESM**.
2. On the left, click on **System Properties** => **System Feature Settings** => **SMDR Options**.
3. Click **Change**.
4. Set **System Identification** to a Unique number.
5. Click **Save**.

NOTE: This alarm will need to be cleared manually by going to **YourSite Explorer** and clicking on Alarms. Select the alarm in question and click the **Snooze** button.

APPLIES TO

CCM 6.0 SP1

Keywords: System Identification Sys ID ALM0077

Last Modified By: amontpetit, Tuesday, September 18, 2012

<http://micc.mitel.com/kb/KnowledgebaseArticle51524.aspx>

Friday, August 12, 2022